



18 cables across in tray
13 tiers of wall PMT cables (yellow) = 234 (228 needed)
7 tiers of floor PMT cables (blue) = 126 (need about 66, but must accommodate heavily used trays)



Clamp pieces made from Stainless or hard plastic



Cable Clamping Scheme